

ABSTRACT

Nanophase WC powder is produced by preparing a precursor including tungsten; producing gas
by vaporizing or sublimating the precursor; carbonizing the gas in the atmosphere without oxygen
5 while maintaining pressure below atmospheric pressure; and condensing the carbonized gas